



### 1010 CL Rotary Scale Clamp Meter



- Rotary scale which presents only one scale in windows at one time to avoid any possible reading errors.
- Pointer lock function freezes the reading in dimly lit or hard to reach places.
- $\Omega$  range ideal for checking the continuity or relays, transformers and motor coils.
- TAUT BAND movement.

### Specifications

ACA	10 / 30 / 100 / 300 / 1000A $\pm 3\%$ of F.S.(50/60Hz)
AC V	150 / 300 / 750V $\pm 3\%$ of F.S.
DC V	—
$\Omega$	2k $\Omega$ $\pm 3\%$ of Scale length
Frequency response	50 / 60Hz for ACA 6A 50-400Hz for ACA 30 / 100 / 300 / 1000A
Dimensions	227(L) $\times$ 73(W) $\times$ 33(D)mm
Conductor size	52mm Max
Weight (battery Included)	Approx. 460g
Safety standard	—

### Accessories

Instruction manual  
Test leads  
Ohm test probe  
Soft pouch



AL-24-1



CAC-3600 B