



# Model ST-3602

## AC/DC Clamp Meter



### ST-3602 AC/DC Clamp Metes

- 3½ digit LCD with maximum reading of 1999.
- Over range indication : "1" is displayed on highest digit.
- Low battery indication: "B" sign appears on the display.
- Response time: approx. 1 second.
- Data hold: for all ranges

### Accessories

Instruction manual  
Test leads  
Soft pouch  
Battery

### Specifications

DC V	200 / 1000V $\pm(1\%rdg+2dgt)$
DC A	200 / 1500A $\pm(2\%rdg+4dgt)$
AC V	200 / 750V $\pm(1.5\%rdg+2dgt)$ (40Hz-1kHz)
AC A	200 / 1500A $\pm(2.0\%rdg+4dgt)$ (40Hz-1kHz)
$\Omega$	200 / 1500 $\Omega$ $\pm(1.5\%rdg+2dgt)$
Diode check	0-1500mV $\pm(1.5\%rdg+2dgt)$
Buzzer	Resistance is less than 100 $\Omega$
Current consumption	Approx. 10mA
Conductor size	55mm Max.
Temperature	Operating: 0°C ~ 40°C
Humidity	85% R.H. Max
Power source	9V(6F22) $\times$ 1
Dimensions	45(L) $\times$ 70(W) $\times$ 41.7(D)mm
Weight	Approx. 480g (battery Included)